ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
2

Ward Name
Chowdeshwari Ward

Street ID
W0371, W0369

Street Name
Dr Ambekdar Govt Ashraya Colony Garudacharapalya, NA

Significant Landmark
Kondappa layout near railway well

Segment No.
2/C-W0371/S101041

Total Length (m)
134.91

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	73.02	77.589955	13.111953	77.590030	13.112560	W0385	DEAD END
2	61.89	77.589960	13.111934	77.590247	13.112418	W0385	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to roads and Drains western side Kondappa layout near railway well in Ward no 02 of Yelahanka Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
1900000

Sanctioned Year
2016

Year
2016 - 2017

Type of Work
Road

Other Work Type

Tender
Not a Tender

Work Details
Improvements to roads and Drains western side Kondappa layout near railway well in Ward no 02 of Yelahanka Sub-Division Yelahanka zone

Job No. / Work Code
002-16-000027

Work Order No.
BBMP/EE (YNK.D)/WO/58/2016-17

Work Order Date
30/04/2016

Period of Extention
90 DAYS

Defect Liability Period From
30/12/2016

Defect Liability Period To
29/12/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
KRIDL

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.

E-Mail ID

Inspection Details

Number of Trees

Any Other Information

Name

RAMANANJEEVAIAH

Date of Inspection

24/02/2017

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	24/02/2017	26/03/2017	COMPLETED
SE	VASU K M	24/02/2017	26/03/2017	COMPLETED
EE	VASU K M	24/02/2017	26/03/2017	COMPLETED
AEE	G.B. PRABHAKAR	24/02/2017	26/03/2017	COMPLETED
AE	RAMANANJEEVAIAH	24/02/2017	26/03/2017	COMPLETED
AE	RAMANANJEEVAIAH	24/02/2017	26/03/2017	COMPLETED